

Fig. 1a




Fig. 1b




Fig. 1c




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7





Fig. 8



Schnitt A-A




Fig. 9






Fig. 10



# BEST AVAILABLE COP

Spring rate

Fig. 11: Federrate

